

ZF6HP21 (BMW GA6HP19Z)

WARNNG: Engine at operating temperature and transmission adaption cleared.

STEP 1 (X 9 times)

1. Standstill
2. Gentle 15%-25% of gas until 4th gear (~ 50km/h) (Drive mode)
3. Continue acceleration lightly (20%-40% of gas) up to 6th gear.
4. Let the vehicle coast to about 40km/h
5. Slightly brake to a standstill.
6. Keep the foot on the brake pedal for 10 seconds.

STEP 2 (X 5 times)

1. Accelerate to 50km/h, using steptronic manual mode to select 3d gear.
2. Continue driving in 3d gear for 3.5 kilometers.
3. Accelerate to 73 Km/h while manually shifting to 5th gear.
4. Lightly gas to 100km/h then let the vehicle freely coast to 65km/h (X 4 times)
5. Gas to 90km/h while shifting manually to 6th gear.
6. Lightly gas to 105km/h then let the vehicle coast freely to 80km/h (X 4 times)
7. Manually shift to 3d gear and repeat Step 2, 5 times.

STEP 3 (X 4 times)

1. Standstill
2. Shift to N
3. Shift to D and wait 5 seconds
4. Shift to N
5. Shift to R and wait for 5 seconds
6. Shift to N.